



Step 1: Turn the box upside/lid down and remove inner packaging material. Remove packaging from threaded rod.

Leave tabletop in the lid of the box to protect the surface from scratching during assembly.

If provided, place metal plate on top of the heating element enclosure and align the holes. Insert the threaded rod (nut down) into the designated hole. Turn the rod clockwise until hand-tight

Step 2: Slide the stand (tube) over the threaded rod, guiding the rod carefully through the designated holes in the brackets at either end of the stand. (graphic 2)

Step 3: Turn the pedestal upside down, position the designated hole on top of the threaded rod. Turn pedestal clockwise until it is firmly connected with the stand and the top of the table. Do not use major force! (graphic 3).

Step 4: Turn the now assembled table to its upright position and level it by rising or lowering the respective adjustment nuts at the bottom of the pedestal.